## Republic of the Philippines **GUIMBA WATER DISTRICT** DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPO **DECEMBER 1-15, 2020**

SAMPLING LOCATION			10 - Hilling 8.2		***********	DAYS OF T	THE MONTH	(Residual	=PPM/Tim	e of Samplir	ng)					REMARKS
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
SAN BERNARDINO	0.27 <b>10:02AM</b>					*										4
STA. VERONICA PUMPING STATION		0.31 8:06AM													4	1
MANGGANG MARIKIT			0.24 10:40AM													4
ST. JOHN				0.28 1:16PM			8									4
SAN ROQUE PUMPING STATION		2.			0.32 12:15PM											1
BALINGOG EAST						0.26 11:49AM										4
STA. CRUZ							0.26 10:42AM									4
TAMPAC 2-3 PUMPING STATION				70				0.33 9:53AM	24							1
SAN MIGUEL									0.26 11:08AM							4
SAN FELIPE										0.22 11:00AM						4
GUUISET				2							0.25 10:55AM					4
SAN RAFAEL PUMPING STATION		× 2	A 11			1 S			# # # # # # # # # # # # # # # # # # #			0.31 11:32AM				1
BALBALINO							7.17						0.28 8:02AM			4
CAWAYANG BUGTONG								13 15 -00 -00 -00		West Barrier B		PULL PARTIES OF THE PURISH OF	3.3.3.1.1	0.27 1:08PM		4
STA. LUCIA	1		du socioco essential								×				0.27 1:19PM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap **RESIDUAL SAMPLERS: REVIEWED By: CERTIFIED By:** 

FRANCIS E. ESQUIVEL

**DIVISION MANAGER B-ENGINEERING** 

**RAUDERICK A. RAMOS** SR. WATER MAINTENANCE MAN-A

ROMMEL G. GRAGASIN

DIVISION MANAGER B-PRODUCTION

ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER

## Republic of the Philippines **GUIMBA WATER DISTRICT** DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT **DECEMBER 16-30, 2020**

SAMPLING LOCATION		DAYS OF THE MONTH ( Residual =PPM/ Time of Sampling)															REMARKS
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
MATURANOC PUMPING STATION	0.33 9:42AM																1
YUSON		0.23 10:29AM															4
BACAYAO BOOSTER PUMPING STATION			0.33 10:29AM														3
STA. ANA				0.25 1:00AM													4
BACAYAO PUMPING STATION					0.32 9:42AM												1
MANACSAC				nc=101=-111		0.27 12:02PM										Name of the second	4
CASONSONG							0.26 10:14AM										4
BANITAN								0.25 2:41PM									4
BAGONG BARRIO						111			0.24 10:18AM								4
BALBALINO										0.25 3:45PM							4
FAIGAL											0.22 9:15AM						4
SAN ANDRES PUMPING STATION												0.32 10:50AM					1
SAN AGUSTIN													0.22 10:58AM				4
BANTUG PUMPING STATION														0.33 8:25AM			1
NAGPANDAYAN															0.27 3:45PM		4
PARTIDA 1																0.26 1:00AM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap **RESIDUAL SAMPLERS: REVIEWED By: CERTIFIED By:** 

**DIVISION MANAGER B-ENGINEERING** SR. WATER MAINTENANCE MAN-A

ROMMEL G. GRAGASIN DIVISION MANAGER B-PRODUCTION

GENERAL MANAGER