

Republic of the Philippines
GUIMBA WATER DISTRICT
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT
FEBRUARY 16-28, 2021


SAMPLING LOCATION	DAYS OF THE MONTH (Residual =PPM/ Time of Sampling)																REMARKS
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
MATURANOC PUMPING STATION	0.32 7:51AM																1
PARTIDA 1		0.27 12:01PM															4
MACATCATUIT			0.24 11:00AM														4
BACAYAO BOOSTER PUMPING STATION				0.33 8:17AM													3
BACAYAO PUMPING STATION					0.33 11:09AM												1
CAWAYANG BUGTONG						0.28 9:21AM											4
GUISET							0.25 8:11AM										4
CALEM								0.22 10:19AM									4
SAN MIGUEL									0.26 8:38AM								4
BANTUG PUMPING STATION										0.32 8:01AM							1
NAGLABRAHAN											0.24 10:43AM						4
SAN ANDRES PUMPING STATION												0.33 10:14AM					1
RUFINA HOMES V PUMPING STATION													0.34 7:46AM				1

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap
RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:


FRANCIS E. ESQUIVEL
DIVISION MANAGER B-ENGINEERING


RAUDERICK A. RAMOS
SR. WATER MAINTENANCE MAN-A


ROMMEL G. GRAGASIN
DIVISION MANAGER B-PRODUCTION


ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER

Republic of the Philippines
GUIMBA WATER DISTRICT
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT
FEBRUARY 1-15, 2021


SAMPLING LOCATION	DAYS OF THE MONTH (Residual =PPM/ Time of Sampling)															REMARKS
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
SAN MARCELINO	0.28 11:04AM															4
STA. VERONICA PUMPING STATION		0.33 7:16AM														1
BANITAN			0.28 11:01AM													4
SAN BERNARDINO				0.24 10:58AM												4
SAN ROQUE PUMPING STATION					0.33 8:53AM											1
STA. ANNA						0.27 11:08AM										4
SAN AGUSTIN							0.25 4:10PM									4
TAMPAC 2-3 PUMPING STATION								0.34 8:33AM								1
MANACSAC									0.25 8:48AM							4
CULONG										0.27 9:29AM						4
STA. LUCIA											0.28 11:00AM					4
SAN RAFAEL PUMPING STATION												0.33 11:26AM				1
BALINGOG WEST													0.27 11:37AM			4
STA CRUZ														0.24 11:37AM		4
BUNOL															0.23 12:01PM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap
RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:


FRANCIS E. ESQUIVEL
DIVISION MANAGER B-ENGINEERING


RAUDERICK A. RAMOS
SR. WATER MAINTENANCE MAN-A


ROMMEL G. GRAGASIN
DIVISION MANAGER B-PRODUCTION


ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER