Republic of the Philippines GUIMBA WATER DISTRICT DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT JANUARY 16-31, 2020

SAMPLING		DAYS OF THE MONTH (Residual =PPM/ Time of Sampling)															REMARKS
LOCATION	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
SAQN ROQUE PUMPING STATION	0.34 10:15AM																1
SAN MIGUEL		0.30 2:31M															4
SUBOL			0.21 2:30PM														4
PASONG INCHIK				0.21 3:15PM													4
BAGONG BARRIO					0.24 2:15PM												4
PARTIDA I						0.27 1:35PM							-				4
BAINGOG WEST							0.29 11:15AM	/									4
BANTUG PUMPING STATION								0.29 11:12AM									1
BACAYAO PUMPING STATION									0.32 9:20AM								1
CARDINAL										0.29 8:48AM							4
MATURANOC PUMPING STATION											0.27 9:30AM						1
MANGGANG MARIKIT												0.26 9:54AM					4
SAN BERNARDINO													0.26 10:28AM				4
CAVITE						700000000000000000000000000000000000000		*CONSCIPETING PPLOTOGRAPHICAL	70.25.000					0.30 10:15AM			4
TAMPAC 2-3 PUMPING STATION															0.30 8:40AM		1
PACAC						7,00,000										0.29 10:45AM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chronination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:

FRANCIS E. ESQUÍVEL CARLVEN M. GUIANG
DIVISION MANAGER B-ENGINEERING DRIVER

ROMMEL G. GRAGASIN

DIVISION MANAGER B-PRODUCTION

ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER

Republic of the Philippines GUIMBA WATER DISTRICT DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT JANUARY 1-15, 2020

SAMPLING LOCATION		DAYS OF THE MONTH (Residual = PPM/ Time of Sampling)														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
CATIMON	0.25 11:32AM														99 97 ANN ANN ANN ANN ANN ANN ANN ANN ANN AN	4
AGCANO	,	0.21 1:39PM														4
MANACSAC			0.28 2:31PM													4
BANTUG PUMPING STATION				0.25 2:15PM												1
SUBOL					0.20 3:12PM											4
TRIALA						0.25 10:09AM	~									4
SAN ANDRES PUMPING STATION					Σ	1	0.29 1:06AM									1
BULAKID								0.28 9:49AM								4
STA.CRUZ									026 11:55AM					CONTRACTOR OF CO		4
SAN RAFAEL PUMPING STATION										0.28 8:20AM						1
PACAC											0.34 4:05PM					4
BULAKID												0.31 1:52PM				4
BACAYAO BOOSTER PUMPING STATION													0.31 9:15AM			3
MANGANG MARIKIT						ette mintet discussivere conservation and clinic delical	ega financia de menumento en en entre en en en en entre en en entre en entre en en entre en en entre en entre e							0.28 10:32AM		4
STA. VERONICA PUMPING STATION	AND THE PROPERTY OF THE PROPER														0.31 10:51AM	1

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:

FRANCIS E. ESQUIVEL

DIVISION MANAGER B-ENGINEERING

CARLUEN M. GUIANG

BRIVER

ROMINEL G. GRAGASIN

DIVISION MANAGER B-PRODUCTION

ENGR. FELIXBERTO C. LEGARDA

GENERAL MANAGER