


Republic of the Philippines  
GUIMBA WATER DISTRICT  
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT  
MARCH 1-15, 2021

SAMPLING LOCATION	DAYS OF THE MONTH ( Residual =PPM/ Time of Sampling)															REMARKS
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
BUNOL	0.25 10:24AM															4
STA. VERONICA PUMPING STATION		0.33 7:08AM														1
YUSON			0.24 10:04AM													4
BANITAN				0.29 9:08AM												4
SAN ROQUE PUMPING STATION					0.32 7:19AM											1
SAN AGUSTIN						0.25 10:21AM										4
BALINGOG EAST							0.28 8:52AM									4
TAMPAC 2-3 PUMPING STATION								0.33 10:33AM								1
MANACSAC									0.27 9:02AM							4
TRIALA										0.28 10:48AM						4
MANGGANG MARIKIT											0.28 10:45AM					4
SAN RAFAEL PUMPING STATION												0.33 10:12AM				1
BALBALINO													0.26 11:33AM			4
BALINGOG WEST														0.28 10:43AM		4
SAN AGUSTIN															0.24 10:12AM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap  
RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:

  
FRANCIS E. ESQUIVEL  
DIVISION MANAGER B-ENGINEERING

  
RAUDERICK A. RAMOS  
SR. WATER MAINTENANCE MAN-A

  
ROMMEL G. GRAGASIN  
DIVISION MANAGER B-PRODUCTION

  
ENGR. FELIXBERTO C. LEGARDA  
GENERAL MANAGER

Republic of the Philippines  
GUIMBA WATER DISTRICT  
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT  
MARCH 16-31, 2021

SAMPLING LOCATION	DAYS OF THE MONTH (Residual =PPM/ Time of Sampling)																REMARKS
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
MATURANOC PUMPING STATION	0.32 7:14AM																1
NAGLABRAHAN		0.25 10:38AM															4
BACAYAO BOOSTER PUMPING STATION			0.31 7:53AM														3
BACAYAO PUMPING STATION				0.32 8:00AM													1
PARTIDA 1					0.26 12:48AM												4
ST. JOHN						0.30 7:16AM											4
CASONGSONG							0.30 9:45AM										4
CAMIING								0.28 8:10AM									4
LAMORITO									0.24 10:26AM								4
BANTUG PUMPING STATION										0.35 9:03AM							1
BALBALINO											0.24 11:00AM						4
SAN ANDRES PUMPING STATION												0.33 9:12AM					1
RUFINA HOMES V PUMPING STATION													0.34 11:51AM				1
BAGONG BARRIO														0.34 10:25AM			4
MACATCATUIT															0.27 9:29AM		4
SAN FELIPE																0.27 10:18AM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap  
RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:

  
FRANCIS E. ESQUIVEL  
DIVISION MANAGER B-ENGINEERING

  
RAUDERICK A. RAMOS  
SR. WATER MAINTENANCE MAN-A

  
ROMMEL G. GRAGASIN  
DIVISION MANAGER B-PRODUCTION

  
ENGR. FELIXBERTO C. LEGARDA  
GENERAL MANAGER