


Republic of the Philippines
GUIMBA WATER DISTRICT
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT
MAY 11-15, 2021

SAMPLING LOCATION	DAYS OF THE MONTH (Residual = FPM/ Time of Sampling)															REMARKS
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
YUZOIN	0.25 1:35PM															4
STA. VERONICA PUMPING STATION		0.33 6:45AM														1
SAN BERNARDINO			0.27 8:48AM													4
BANITAN				0.28 8:37AM												4
SAN ROQUE PUMPING STATION					0.33 7:36AM											1
LENNEC						0.29 10:17AM										4
GUISET							0.29 10:24AM									4
TAMPA 2-3 PUMPING STATION								0.34 8:51AM								1
STA. CRUZ									0.30 9:45AM							4
MANAC SAC										0.28 9:48AM						4
BALINGOG EAST											0.30 3:35PM					4
SAN RAFAEL PUMPING STATION												0.34 4:18PM				1
SUBOL													0.29 9:14AM			4
MANAC SAC														0.25 10:01AM		4
CABALLERO															0.29 11:15AM	4

DAILY SAMPLING (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap
RESIDUAL SAMPLERS:

REVIEWED BY:

CERTIFIED BY:


FRANCIS E. ESQUIVEL
DIVISION MANAGER B-ENGINEERING


RAUDERICK A. RAMOS
SR. WATER MAINTENANCE MAN-A


ROMMEL S. GRAGASIN
DIVISION MANAGER B-PRODUCTION


ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER

Republic of the Philippines
GUIMBA WATER DISTRICT
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT
MAY 16-31, 2021


SAMPLING LOCATION	DAYS OF THE MONTH (Residual =PPM / Time of Sampling)																REMARKS
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
MATURANOC PUMPING STATION	0.33 7:51AM																1
CAVITE		0.31 7:18AM															4
BACAYAO BOOSTER PUMPING STATION			0.32 9:11AM														3
BACAYAO PUMPING STATION				0.32 8:42AM													1
NAGPANDAYAN					0.28 9:50AM												4
BUNOL						0.25 10:33AM											4
SAN MIGUEL							0.27 1:35PM										4
MACATCATUIT								0.29 5:02AM									4
SINULATAN									0.27 10:45AM								4
BANTUG PUMPING STATION										0.33 9:14AM							1
MAYBUBOV											0.24 10:15AM						4
SAN ANDRES PUMPING STATION												0.34 7:26AM					1
STA. LUCIA													0.33 11:20AM				4
PACAC														0.33 11:15AM			4
RUFINA HOMES V PUMPING STATION															0.35 7:00AM		1
STA. ANA																0.27 3:15AM	4

DAILY SAMPLING (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap
RESIDUAL SAMPLERS:

REVIEWED BY:

CERTIFIED By:


FRANCIS E. ESQUIVEL
DIVISION MANAGER B-ENGINEERING


RAUDERICK A. RAMOS
SR. WATER MAINTENANCE MAN


ROMMEL A. GRAGASIN
DIVISION MANAGER B-PRODUCTION


ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER