


Republic of the Philippines
GUIMBA WATER DISTRICT
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT
NOVEMBER 1-15, 2021

SAMPLING LOCATION	DAYS OF THE MONTH (Residual =PPM/ Time of Sampling)															REMARKS
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
LENNEC	0.30 8:20AM															4
STA. VERONICA PUMPING STATION		0.32 7:40AM														1
AGCANO			0.25 9:40AM													4
CABARUAN				0.28 10:36AM												4
SAN ROQUE PUMPING STATION					0.30 10:08AM											1
TAMPAC 1						0.29 10:00AM										4
CAMIING							0.28 8:20AM									4
BANTUG PUMPING STATION								0.32 9:00AM								1
MACATCATUIT									0.29 8:30AM							4
SAN BERNARDINO										0.26 8:15AM						4
TRIALA											0.28 7:25AM					4
MATURANOC PUMPING STATION												0.32 7:16AM				1
BALBALINO													0.28 9:00AM			4
ST JOHN														0.30 7:30AM		4
BAGONG BARRIO															0.25 8:00AM	4


DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap
RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:


FRANCIS E. ESQUIVEL
DIVISION MANAGER B-ENGINEERING


RAUDERICK A. RAMOS
SR. WATER MAINTENANCE MAN-A


ROMMEL G. GRAGASIN
DIVISION MANAGER B-PRODUCTION


ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER

GUIMBA WATER DISTRICT
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT
NOVEMBER 16-30, 2021

SAMPLING LOCATION	DAYS OF THE MONTH (Residual =PPM/ Time of Sampling)																REMARKS
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
BACAYAO BOOSTER PUMPING STATION	0.32 8:15AM																3
BACAYAO PUMPING STATION		0.33 10:20AM															1
BUNOL			0.27 7:50AM														4
SAN MARCELINO				0.23 8:00AM													4
SAN ANDRES PUMPING STATION					0.34 1:56PM												1
BALINGOG WEST						0.30 2:38 PM											4
CARDINAL							0.24 7:46AM										4
SAN RAFAEL PUMPING STATION								0.33 9:47AM									1
FAIGAL									0.26 7:51AM								4
LAMORITO										0.23 8:15AM							4
CAVITE											0.30 10:25AM						4
TAMPAC 2-3 PUMPING STATION												0.34 9:00AM					1
MAYBUBON													0.24 8:01AM				4
NARVACAN 1 PUMPING STATION														0.32 8:41AM			1
RUFINA HOMES V PUMPING STATION															0.33 10:00AM		1

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap
 RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:


FRANCIS E. ESQUIVEL
 DIVISION MANAGER B-ENGINEERING


RAUDERICK A. RAMOS
 SR. WATER MAINTENANCE MAN-A


ROMMEL G. GRAGASIN
 DIVISION MANAGER B-PRODUCTION


ENGR. FELIXBERTO L. LEGARDA
 GENERAL MANAGER