## GUIMBA WATER DISTRICT DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT OCTOBER 16-31, 2021

SAMPLING LOCATION		DAYS OF THE MONTH ( Residual =PPM/ Time of Sampling)															REMARKS
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
BACAYAO BOOSTER PUMPING STATION	0.32 7:30AM																3
BACAYAO PUMPING STATION		0.32 8:16AM															1
CARDINAL			0.24 8:00AM														4
NAGLABRAHAN				0.25 7:48AM													4
SAN ANDRES PUMPING STATION					0.32 7:38AM												1
YUSON						0.25 8:16AM											4
CATIMON							0.23 8:04AM										4
SAN RAFAEL PUMPING STATION								0.32 9:30AM									1
NAGPANDAYAN	S-12-110-2								0.28 8:36AM								4
SINULATAN										0.27 7:45AM							4
SAN MIGUEL											0.24 8:33AM						4
TAMPAC 2-3 PUMPING STATION												0.33 8:55AM					1
STA.ANA													0.28 7:46AM				4
PARTIDA 1														0.24 8:30AM			4
RUFINA HOMES V PUMPING STATION															0.34 8:30AM		1
ST. JOHN																0.30 9:00AM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap RESIDUAL SAMPLERS:

CERTIFIED By:

FRANCIS E. ESQUIVEL
DIVISION MANAGER B-ENGINEERING

RAUDERICK A. RAMOS
SR. WATER MAINTENANCE MAN-A

BOMMEL G. GRAGASIN

DIVISION MANAGER B-PRODUCTION

ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER

## Republic of the Philippines GUIMBA WATER DISTRICT DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT OCTOBER 1-15, 2021

SAMPLING LOCATION		DAYS OF THE MONTH ( Residual = PPM/ Time of Sampling)														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	REMAR
CASONGSONG	0.28 7:45AM															4
STA. VERONICA PUMPING STATION		0.33 7:19AM														1
SAN BERNARDINO			0.25 10:00AM													4
CABARUAN				0.26 7:42AM												4
SAN ROQUE PUMPING STATION					0.32 10:00AM											1
LENNEC						0.29 7:52AM				l l					1	4
BALINGOG EAST							0.30 8:10AM									4
BANTUG PUMPING STATION								0.33 9:16AM								1
TRIALA									0.28 1:30PM							4
BALBALINO										0.27 8:00AM						4
MANGANG MARIKIT											0.30 8:12AM					4
MATURANOC PUMPING STATION							7					0.33 10:00AM				1
CABALLERO				7/1									0.25 7:35AM			4
BUNOL														0.23 7:38AM		4
SAN MAECELINO															0.25 8:40AM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap REVIEWED By:

CERTIFIED By:

FRANCIS E. ESQUIVEL
DIVISION MANAGER B-ENGINEERING

SR. WATER MAINTENANCE MAN-A

ROMMEL G. GRAGASIN
DIVISION MANAGER B-PRODUCTION

ENGR. FELIXBERTO CLEGARDA GENERAL MANAGER

Republic of the Philippines