

Republic of the Philippines
GUIMBA WATER DISTRICT
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPORT
SEPTEMBER 16-30, 2020


SAMPLING LOCATION	DAYS OF THE MONTH (Residual =PPM/ Time of Sampling)																REMARKS
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	
MATURANOC PUMPING STATION	0.33 7:49AM																1
BACAYAO BOOSTER PUMPING STATION		0.32 9:12AM															4
CABALLERO			0.25 2:52PM														4
MATURANOC PUMPING STATION				0.32 7:25AM													4
BACAYAO PUMPING STATION					0.32 9:16AM												3
NAGLABRAHAN						0.23 9:01AM											4
PARTIDA 1							0.28 1:29PM										4
BALBALINO								0.27 2:40PM									1
CATIMON									0.26 2:41PM								4
SARANAY										0.29 2:26PM							4
CAWAYAN BUGTONG											0.27 8:27AM						4
TABING ILOG (CAINGIN)												0.21 3:08PM					4
SAN MIGUEL													0.24 3:41PM				4
BANTUG PUMPING STATION														0.33 7:39AM			4
SAN ANDRES PUMPING STATION															0.30 7:18AM		1

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap
RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:


FRANCIS E. ESQUIVEL
DIVISION MANAGER B-ENGINEERING


RAUDERICK A. RAMOS
SR. WATER MAINTENANCE MAN-A


ROMMEL G. GRAGASIN
DIVISION MANAGER B-PRODUCTION


ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER

Republic of the Philippines
GUIMBA WATER DISTRICT
DAILY CHLORINE DIOXIDE RESIDUAL MONITORING REPO
SEPTEMBER 1-15, 2020

SAMPLING LOCATION	DAYS OF THE MONTH (Residual =PPM/ Time of Sampling)															REMARKS
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
BUNOL	0.22 2:02PM															4
STA. VERONICA PUMPING STATION		0.32 1:33PM														1
MANGANG MARIKIT			0.27 10:17AM													4
SAN BERNARDINO				0.26 10:39AM												4
SAN ROQUE PUMPING STATION					0.3 2:26PM											1
TRIALA						0.27 10:02AM										4
YUZON							0.23 1:42PM									4
TAMPAC 2-3 PUMPING STATION								0.31 7:16AM								1
SINULATAN									0.25 2:16PM							4
CAMIING										0.27 1:48PM						4
MANACSAC											0.28 9:37AM					4
SAN RAFAEL PUMPING STATION												0.32 9:25AM				1
BALINGOG EAST													0.26 10:20AM			4
FAIGAL														0.22 2:01PM		4
STA CRUZ															0.27 2:48PM	4

DAILY SAMPLING: (1) Nearest point from every water source where full chlorination has been obtained (2) Nearest point of every distribution dead-end (3) nearest point reservoir outlet (4) Concessionaire's Tap

RESIDUAL SAMPLERS:

REVIEWED By:

CERTIFIED By:


FRANCIS E. ESQUIVEL
DIVISION MANAGER B-ENGINEERING


RAUDERICK A. RAMOS
SR. WATER MAINTENANCE MAN-A


ROMMEL G. GRAGASIN
DIVISION MANAGER B-PRODUCTION


ENGR. FELIXBERTO C. LEGARDA
GENERAL MANAGER